
Understanding the upkeep symbols





Drying	
Ø	Do not tumble dry
	This is the case for all chain saw protective clothing. In this case, line drying after spinning is advised (instructions and advice in the usage note) Tumble drying allowed
O	<u>One point:</u> Drying at moderated temperature (60 °C maximum)
$oldsymbol{O}$	Two points: Drying at normal temperature (80 °C maximum)
\odot	
Ironing	
×	Do not iron
2	Iron
ā	Iron on cool (110 °C)
	Iron on hot (150 °C)
	lron on very hot (200 °C)

Professional cleaning

X	Do not dry clean
P	Dry cleaning with perchloroethylene solvents, petrol-based solvents (mineral essences).
Ø	One hyphen: Reduce washing (quantity of water, machine stress, temperature of wash, drying temperature).
P	<u>Two hyphens:</u> Strong reduction of washing (quantity of water, machine stress, temperature of wash, drying temperature)
W	Water-washable by professionals

